

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: NOVEMBER 2005

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "CI-208-020320")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "PE-214-020320")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)

CP (Complaint)

MD (Manufacturer Defect)

ID (Part 574)

MI (Manufacturer Inquiry)

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive

FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
27	202	Head Restraints	Vehicle-15	TEST
28	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
29	204	Steering Control Rearward Displacement	Vehicle-17	TEST
30	205	Glazing Materials (Inspection)	Equipment	Insp.-6
31	206	Door Locks & Door Retention Components	Equip.-8	TEST
32	207	Seating Systems	Vehicle-18	TEST
33	208	Occupant Crash Protection	Vehicle-19	TEST
34	209	Seat Belt Assemblies	Equip.-9	TEST

35	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
36	212	Windshield Mounting	Vehicle-21	TEST
37	213	Child Restraint Systems	Equip.-10	TEST
38	214	Side Impact Protection	Vehicle-22	TEST
39	216	Roof Crush Resistance	Vehicle-23	TEST
40	217	Bus Window Retention & Release	Vehicle-24	TEST
41	218	Motorcycle Helmets	Equip.-11	TEST
42	219	Windshield Zone Intrusion	Vehicle-25	TEST
43	220	School Bus Rollover Protection	Vehicle-26	TEST
44	221	School Bus Body Joint Strength	Vehicle-27	TEST
45	222	School Bus Passenger Seating	Vehicle-28	TEST
46	223	Rear Impact Guards	Equip.-12	TEST
47	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
48	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
49	301	Fuel System Integrity	Vehicle-30	TEST
50	302	Flammability of Interior Materials	Equip.-13	TEST
51	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
52	304	CNG Fuel Container Integrity	Equip.-14	TEST
53	305	Electric Vehicles	Vehicle-32	TEST
54	401	Interior truck Release	Vehicle	TEST
55	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 34 vehicle standards, 14 equipment standards, 7 inspection standards				

REPORTS ACCEPTED DURING OCTOBER 2005 FOR FY 2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA.
Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO.
124	KAR 001	SUZUKI	2005 SUZUKI RENO 4-DOOR H/BACK	PASS 638062
124	KAR 002	GMC	2005 CHEVROLET AVEO 4-DOOR SEDAN	PASS 638064
124	KAR 003	MITSUBISHI	2005 MITSUBISHI LANCER 4-DOOR SEDAN	PASS 638063
201	MGA 003	GMC	2005 CHEVROLET MALIBU 4-DOOR SEDAN	PASS 638057
201	MGA 005	HYUNDAI	2005 HYUNDAI TUSCON MPV 4-DOOR	PASS 638037
201	MGA 007	NISSAN	2005 INFINITI FX35 MPV 4-DOOR	PASS 638042
208	MGA 008	JAGUAR	2005 JAGUAR X-TYPE 4-DOOR SEDAN	FAIL-I ¹ 638040
212	MGA 008	JAGUAR	2005 JAGUAR X-TYPE 4-DOOR SEDAN	PASS 638040
221	MGA 005	BLUE BIRD	2005 BLUE BIRD VISION SCHOOL BUS	PASS 638036
301	KAR 001	SUZUKI	2005 SUZUKI RENO 4-DOOR H/BACK	PASS 638058
301	KAR 002	GMC	2005 CHEVROLET AVEO 4-DOOR SEDAN	PASS 638059
301	KAR 003	MITSUBISHI	2005 MITSUBISHI LANCER 4-DOOR SEDAN	PASS 638060
301	KAR 004	VOLKSWAGEN	2005 VOLKSWAGEN GOLF 4-DOOR H/BACK	PASS 638061
301	MGA 008	JAGUAR	2005 JAGUAR X-TYPE 4-DOOR SEDAN	PASS 638040

REPORTS ACCEPTED DURING OCTOBER 2005 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA.
Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO.
206	MGA 001	FORD	2006 FORD MUSTANG DOOR LATCH/HINGE	PASS 638039
206	MGA 002	FORD	2006 FORD F-250 DOOR LATCH/HINGE	PASS 638043
206	MGA 003	FORD	2006 FORD TAURUS DOOR LATCH/HINGE	PASS 638044
214	CAL 001	SUBARU	2006 SUBARU B9 TRIBECA MPV 4-DOOR	PASS 638056

¹ Owner's manual omission.

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L – LABELING

TIRE REPORTS ACCEPTED DURING OCTOBER 2005 FOR FY 2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA.
Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	RESULT/ HSNO.
575	UTG 157	TOYO RUBBER INDUSTRY CO. LTD.	2005 NITTO NT450 EXTREME PERF. CX8K4NH1904	PASS 6277043
575	UTG 158	TOYO RUBBER INDUSTRY CO. LTD.	2005 NITTO NT450 EXTREME PERF. CX8K4NH1904	PASS 6277044
575	UTG 161	TOYO RUBBER INDUSTRY CO. LTD.	2005 NITTO NT460 PREMIUM	PASS 6277045
575	UTG 162	TOYO RUBBER INDUSTRY CO. LTD.	2005 NITTO NT460 PREMIUM CXF14D10404	PASS 6277046
575	UTG 169	YOKOHAMA TIRE CORP.	2005 YOKOHAMA AVID V4S CC8J8XD4504	PASS 6277047
575	UTG 170	YOKOHAMA TIRE CORP.	2005 YOKOHAMA AVID V4S CC8J8XD4504	PASS 6277048
575	UTG 173	HANKOOK TIRE MANUFACTURING	2005 HANKOOK MILEAGE PLUS II T7BMDFH2404	PASS 6277050
575	UTG 174	HANKOOK TIRE MANUFACTURING	2005 HANKOOK MILEAGE PLUS II T7BMDFH2404	PASS 6277051
575	UTG 177	HANKOOK TIRE MANUFACTURING	2005 DELTA FORTUNE T7HLB9P1004	PASS 6277052
575	UTG 178	HANKOOK TIRE MANUFACTURING	2005 DELTA FORTUNE T7HLB9P1104	PASS 6277053
575	UTG 181	KELLY-SPRINGFIELD TIRE CO.	2005 ARIZONIAN SILVER EDITION PJX0YMLR1704	PASS 6277054
575	UTG 182	KELLY-SPRINGFIELD TIRE CO.	2005 ARIZONIAN SILVER EDITION PJX0YMLR1704	PASS 6277055
575	UTG 189	GENERAL TIRE CO.	2005 CONTINENTAL CONTI EXTREME ACX03LL0504	PASS 6277056
575	UTG 190	GENERAL TIRE CO.	2005 CONTINENTAL CONTI EXTREME ACX03LL0504	PASS 6277057
575	UTG 193	COOPER TIRE & RUBBER CO.	2005 COOPER ZEON ZPT U90HC842404	PASS 6277058
575	UTG 194	COOPER TIRE & RUBBER CO.	2005 COOPER ZEON ZPT U90HC842404	PASS 6277059
575	UTG 197	SUMITOMO RUBBER IND. LTD.	2005 SUMITOMO HTR+ U28JAMCR1405	PASS 6277060
575	UTG 198	SUMITOMO RUBBER IND. LTD.	2005 SUMITOMO HTR+ U28JAMCR1405	PASS 6277061
575	UTG 201	UNIROYAL GOODRICH TIRE CO.	2005 B.F. GOODRICH TRACTION T/A BEXVTJ112504	PASS 6277062
575	UTG 202	UNIROYAL GOODRICH TIRE CO.	2005 B.F. GOODRICH TRACTION T/A BEXVTJ112504	PASS 6277063
575	UTG 205	NEXEN TIRE CORP.	2005 NEXEN RADIAL N3000 8E6FMK2104	PASS 6277064
575	UTG 206	NEXEN TIRE CORP.	2005 NEXEN RADIAL N3000 8E6FMK2304	PASS 6277065
575	UTG 209	BRIDGESTONE TOSU PLANT	2005 BRIDGESTONE DUELER H/P EJKKCKD1304	PASS 6277066

TIRE REPORTS ACCEPTED DURING OCTOBER 2005 FOR FY 2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA.
Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	RESULT/ HSNO.
575	UTG 210	BRIDGESTONE TOSU PLANT	2005 BRIDGESTONE DUELER H/P EJKKCKD1304	PASS 6277067
575	UTG 213	NANKANG RUBBER CO.	2005 PERFORMANCE X/P NS ALL-SPORT U8KN6491904	PASS 6277068
575	UTG 214	NANKANG RUBBER CO.	2005 PERFORMANCE U8KN6491904	PASS 6277069

Note: The tire description usually includes an ID number. The tire ID number changes by production week and it is not a tire serial number. Tire ID numbers that are identical indicate that the tires were manufactured during the same week, not that they are the same tire.

COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH OCTOBER 2005
(CI NUMBER SYSTEM EXAMPLE: "CI-208-041220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2004)

NONE

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH OCTOBER 2005
(PE NUMBER SYSTEM EXAMPLE: "PE-208-041220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2004)**

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-120-050825	US Bus Corp./2005 US Bus Universe/Tire support GAWR	CP
PE-201-041110	Ford Motor Co./2005 Ford Escape/A-Pillar Hic > 1000	CT
PE-201-050228	Mazda North American Operations/2004 Mazda 6/Interior compartment door test	CT
PE-201-050325	General Motors Corp./2005 Buick Lactosse/Upper roof rail target (Ur2):1164 HIC<1000 HIC	CT
PE-208-050323	Toyota Motor Co./2005 Toyota Corolla/Passenger neck compression	CT
PE-208-050405	Mercedes Benz/2005 Mercedes C230/LRD test failure 5FHIII	CT
PE-221-050706	Corbeil International/2005 Corbeil/30 passenger school bus/Joint tensil strength less than 60%	CT

PEs OPENED SINCE LAST REPORT

NONE

PEs CLOSED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-121-041101	Indiana Phoenix Inc./2004 Air Brakes/Data request/Closed by NHTSA 8/26/2005
PE-222-050525	Blue Bird/2005 Blue Bird Vision/Barrier position and rear surface area/Closed by NHTSA 10/01/2005

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfr. Inquiry
MD Mfr. Defect